

Daftar Lelang Floor Mobil - LELANG ONLINE VAGANZA TIMUR | 16/05/2024 (15)
KOTA LELANG ONLINE VAGANZA TIMUR (LOV) / -

KATALOG INI HANYA SEBAGAI PANDUAN SAJA. BUKAN SEBAGAI PEDOMAN ATAU SEBAGAI BAHAN ACUAN COMPLAIN

SmartBID melelang unit apa adanya, peserta lelang wajib melakukan cek fisik kendaraan dan dokumen dengan sebaik-baiknya. Pemenang lelang telah dianggap sudah memahami kondisi dan dokumen kendaraan yang telah dimenangkan. Deposit dan pelunasan unit Lelang SmartBID hanya melalui transfer Bank Central Asia, Tbk (BCA) a/n PT. Anugerah Lelang Indonesia, nomor rekening : 4688897988 (Sidoarjo), 4686088588 (Semarang), 4687088688 (Tangerang), 4688670088 (Makassar) .

Note:

Setiap unit dikenakan biaya administrasi sebesar: **Rp. 3.000.000,-**
 Khusus untuk unit dengan harga terbentuk di atas Rp. 333.000.000,- dikenakan admin fee 1% dari harga terbentuk.

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
1	L 1721 FX	TOYOTA RUSH S	2020	AT	1496	PUTIH	Rp. 192.000.000	BENSIN	130598	C	C	C	9 HARI KERJA	ADA 2024-02-10	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC AWAL +62 895-3231-57272 // FAKTUR FOTOCOPY LEGALISIR																	
2	D 1787 SGE	HONDA JAZZ GD3 1.5 IDSI AT	2005	AT	1492	BIRU METALIK	Rp. 16.000.000	BENSIN	283878	E	D	D	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC HENDRO 081211600111 // ADA PERBEDAAN NOMOR MESIN 7 DIGIT PADA FISIK L15A25800849 PADA DOKUMEN BPKB L15A22908801 // MESIN PADA FISIK BONGKARAN // NOMOR MESIN PADA FISIK GANTIAN // MESIN KANIBALAN UNIT DILELANG APA ADANYA PEMENANG LELANG WAJIB TTD SURAT PERNYATAAN DIATAS MATERAI // PEMENANG LELANG DIANGGAP SUDAH MENGETAHUI KONDISI UNIT DAN PERMASALAHAN YANG DITIMBULKAN DIKEMUDIAN HARI DILUAR TANGGUNG JAWAB SMARTBID //CASHBACK RP 3.500.000																	
3	DD 1929 UU	DAIHATSU XENIA X	2021	AT	1329	ABU ABU METALIK	Rp. 149.000.000	BENSIN	18904	C	B	B	9 HARI KERJA	ADA 2024-12-03	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU//KOMPLEN MAKSIMAL SEBULAN SETELAH UNIT DIMENANGKAN //PIC DEDE 082194075310																	
4	S 1428 U	DAIHATSU AYL A 1.2R	2021	MT	1197	KUNING METALIK	Rp. 68.000.000	BENSIN	41879	D	E	D	9 HARI KERJA	ADA 2022-06-10	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC AWAL +62 895-3231-57272																	
5	L 888 AVE	HONDA HRV 1.5L SE CVT	2022	MT	1498	ABU ABU BULAN METALIK	Rp. 293.000.000	BENSIN	15381	C	C	C	9 HARI KERJA	ADA 2024-09-22	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT SERTA DOKUMEN TERLEBIH DAHULU// PIC AWAL +62 895-3231-57272																	
6	BH 8609 BL	DAIHATSU GRAN MAX PICK-UP	2019	MT	1495	HITAM	Rp. 57.000.000	BENSIN	134104	D	C	C	9 HARI KERJA	ADA 2023-06-02	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC AWAL +62 895-3231-57272																	
7	DD 1052 SU	DAIHATSU XENIA	2011	MT	1298	ABU ABU METALIK	Rp. 54.000.000	BENSIN	227443	D	C	C	9 HARI KERJA	ADA 2023-09-23	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU//KOMPLAIN MAKSIMAL SEBULAN SETELAH UNIT DIMENANGKAN //PELUNASAN H+3 SETELAH LELANG //PIC RUDAL : 0853-9702-6168// UNIT MENDAPAT CASHBACK 3.500.000																	
8	DB 1492 MG	DAIHATSU XENIA	2011	MT	989	HITAM METALIK	Rp. 47.000.000	BENSIN	109981	C	C	D	9 HARI KERJA	ADA 2023-06-06	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //PIC ERWIN 0852-5532-9221// UNIT MENDAPAT CASHBACK 3.500.000																	
9	DW 8897 AK	DAIHATSU GRANMAX PICK-UP	2020	MT	1495	PUTIH	Rp. 73.000.000	BENSIN	132290	D	D	D	9 HARI KERJA	ADA 2024-03-12	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
KEUR T/A	SPH T/A	FORM A T/A	SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //PIC MIFTAH 082196768826// NOMOR MESIN TERPISAH DENGAN MESIN// UNIT MENDAPAT CASHBACK 2.000.000														
10	AA 1281 CJ	TOYOTA YARIS S	2010	AT	1497	HITAM METALIK	RP. 28.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT HARAP DI CEK DAHULU // UNIT TIDAK DICEKLIST OLEH TIM SMARTBID // UNIT BERADA DI POOL TNT // BPK. APRIYADI 0853-9827-9880//_COPY FAKTUR TA // FENDER REPAIR (RR-R) FOG LAMP (R) ELECTRIC MIRROR (R) MIRROR (L) FENDER REPAIR (FR-L) BUMPER REPLACE (FR) DOOR REPAIR (FR-L) FENDER REPAIR (FR-R) HEADLIGHT (FR-L) FOG LAMP (L) DOOR REPAIR (FR-R) ENGINE HOOD REPAIR MIRROR (R) FENDER REPAIR (RR-L) DOOR REPAIR (RR-L) HEADLIGHT (FR-R) ELECTRIC MIRROR (L) SIDE SKIRT REPAIR (L) SIDE SKIRT REPAIR (R) DOOR REPAIR (RR-R) GRILLES, BOLT CRANE AND JACK CARPET CARSEAT (FR-L) INTERIOR SALOON TOOL KIT CARSEAT (FR-R) GEAR LEVER COVER GEAR LEVER _GASKET COVER HEAD RIM (FR-R) GASKET CYLINDER HEAD ENGINE SERVICES (HEAVY) SPRING (FR) SPRING (RR) COIL IGNITION FAN BELT RIM (RR-R) RIM (RR-L) BRAKE MASTER BRAKE PAD (RR) TIRE (RR-R) TIRE (SPARE) TIRE (RR-L) RACK STEER ENGINE DYNAMO STARTER RIM (FR-L) TIRE (FR-L) SPARK PLUG(S) ENGINE COVER VALVE GEAR BOX OVERHAUL SHOCBREAKERS (FR) TIRE (FR-R) BRAKE PAD (FR) BATTERY INJECTOR SHOCBREAKERS (RR// UNIT MENDAPAT CASHBACK 3.000.000																	
11	DB 8289 AO	MITSUBISHI L300 PU	2012	MT	2477	HITAM KANZAI	RP. 27.000.000	SOLAR	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // UNIT DI TERNATE LORONG JERUK RT/RW 007/002 KEL UBO-UBO KEC TERNATE SELATAN KOTA TERNATE MALUKU UTARA // TAILLIGHT (RR-L) DOOR REPAIR (FR-L) BUMPER REPAIR (FR) CARGO PANEL REPAIR (RR-R) HEADLIGHT (FR-R) CARGO PANEL REPAIR (RR) TAILLIGHT (RR-R) FENDER REPAIR (FR-L) FENDER REPAIR (FR-R) HEADLIGHT (FR-L) CARGO PANEL REPAIR (DECK) CARGO PANEL REPAIR (RR-L) DOOR REPAIR (FR-R) TOOL KIT DOOR TRIM (FR-L) DOOR TRIM (FR-R) CARSEAT (FR-R) CARPET DASHBOARD INTERIOR SALOON CARSEAT (FR-L) HEAD UNIT BOLT CRANE AND JACKSHOCBREAKERS (RR) TIRE (FR-R) GASKET COVER HEAD RADIATOR FAN SPRING (RR) SPRING (FR) AIR FILTER FAN BELT INJECTOR TIRE (RR-L) TIRE (RR-R) WHEEL BEARING (FR) WHEEL BEARING (RR) SHOCBREAKERS (FR) BRAKE PAD (RR) BRAKE PAD (FR) GASKET CYLINDER HEAD COIL IGNITION TIRE (SPARE) ENGINE SERVICES (LIGHT) CLUTCH PLATE SPARK PLUG(S) TIRE (FR-L)// UNIT MENDAPAT CASHBACK 3.000.000																	
12	DB 1157 QR	TOYOTA INNOVA G DIESEL	2014	MT	2494	SILVER METALIK	RP. 172.000.000	SOLAR	266416	D	C	D	9 HARI KERJA	ADA 2024-01-18	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //PIC ERWIN 0852-5532-9221// FAKTUR COPYAN// UNIT MENDAPAT CASHBACK 3.500.000																	
13	DE 1773 AG	DAIHATSU TERIOS	2016	MT	1495	PUTIH	RP. 106.000.000	BENSIN	48043	D	D	E	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT SERTA DOKUMEN TERLEBIH DAHULU //KOMPLEN MAKSIMAL SEBULAN SETELAH UNIT DILUNASI DAN DITERIMA LEWAT DARI SEBULAN SUDAH TIDAK MENGAJUKAN KOMPLEN // ARIF: +62 852-4444-2875																	
14	DE 1856 AD	SUZUKI ERTIGA DX	2012	MT	1373	BIRU MUDA METALIK	RP. 66.000.000	BENSIN	93934	D	D	D	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT SERTA DOKUMEN TERLEBIH DAHULU //KOMPLEN MAKSIMAL SEBULAN SETELAH UNIT DILUNASI DAN DITERIMA LEWAT DARI SEBULAN SUDAH TIDAK MENGAJUKAN KOMPLEN // ARIF: +62 852-4444-2875// UNIT MENDAPAT CASHBACK 3.000.000																	
15	DM 1024 EA	SUZUKI ERTIGA	2013	MT	1373	ABU ABU METALIK	RP. 0	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PIC BPK. APRIYADI 0853-9827-9880//_HEADLIGHT (FR-L) FENDER REPAIR (FR-R) HEADLIGHT (FR-R) ENGINE HOOD REPAIR DOOR REPAIR (RR-R) DOOR REPAIR (RR-L) FENDER REPAIR (FR-L) DOOR REPAIR (FR-L) FENDER REPAIR (RR-L) DOOR REPAIR (FR-R) ROOF REPAIR DOOR REPAIR (TRUNK) FENDER REPAIR (RR-R) BUMPER REPAIR (RR) BUMPER REPAIR (FR)_CARSEAT (FR-L) CARSEAT (FR-R) INTERIOR SALOON TOOL KIT BOLT CRANE AND JACK_TIRE (FR-R) FAN BELT SPRING (RR) RIM (RR-R) RIM (RR-L) SPARK PLUG(S) TIRE (RR-L) GASKET CYLINDER HEAD CLUTCH PLATE SHOCBREAKERS (RR) FUEL PUMP SPRING (FR) TIRE (FR-L) INJECTOR TIRE (RR-R) COIL IGNITION TIRE (SPARE) ENGINE SERVICES (HEAVY) GASKET COVER HEAD BRAKE PAD (FR) BRAKE PAD (RR) SHOCBREAKERS (FR) RADIATOR FAN RACK STEER BATTERY																	
16	DB 8969 LM	DAIHATSU GRANMAX PICK-UP	2021	MT	1298	HITAM	RP. 59.000.000	BENSIN	110627	D	D	D	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU//KOMPLEN MAKSIMAL SEBULAN SETELAH UNIT DIMENANGKAN // PIC DEDE 082194075310//																	
17	DW 8941 BG	DAIHATSU GRANMAX PICK-UP	2015	MT	-	HITAM	RP. 56.000.000	BENSIN	347092	D	D	D	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC DEDE 082194075310																	
18	KT 8854 GH	DAIHATSU GRANMAX PICK-UP	2019	MT	1495	ABU ABU METALIK	RP. 30.000.000	BENSIN	0	D	D	E	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
KEUR T/A	SPH T/A	FORM A T/A	EBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT SERTA DOKUMEN TERLEBIH DAHULU //KOMPLEN MAKSIMAL SEBULAN SETELAH UNIT DILUNASI DAN DITERIMA LEWAT DARI SEBULAN SUDAH TIDAK MENGAJUKAN KOMPLEN//PIC PUTRA :0813-5153-9927 // ADA PERBEDAAN WARNA PADA FISIK HITAM PADA BPKB ABU-ABU METALIK// CASHBACK RP 3.500.000														
19	DB 1898 QL	NISSAN LIVINA GRAND1.5X-GEAR	2009	MT	1498	ABU ABU TUA METALIK	RP. 40.000.000	BENSIN	202572	C	C	C	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC ERWIN 0852-5532-9221																	
20	DD 8115 ST	DAIHATSU GRAN MAX PICK-UP BOX	2016	MT	1495	HITAM	RP. 73.000.000	BENSIN	91124	D	D	D	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC DEDE : +62 821-9407-5310// UNIT MENDAPAT CASHBACK 3.000.000																	
21	DD 8326 EK	DAIHATSU GRANMAX PUACPS1.5FH	2021	MT	1495	HITAM	RP. 87.000.000	BENSIN	75233	D	D	D	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU//KOMPLEN MAKSIMAL SEBULAN SETELAH UNIT DIMENANGKAN // PIC DEDE 082194075310// UNIT MENDAPAT CASHBACK 1.500.000																	
22	DP 1134 AU	TOYOTA AVANZA 1.3G	2011	MT	1298	HITAM METALIK	RP. 51.000.000	BENSIN	225302	D	C	C	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU//KOMPLAIN MAKSIMAL SEBULAN SETELAH UNIT DIMENANGKAN //PELUNASAN H+3 SETELAH LELANG //PIC RUDAL : 0853-9702-6168// UNIT MENDAPAT CASHBACK 3.500.000																	
23	PA 8839 AC	MITSUBISHI COLT FESUPERHD(4X2)	2015	MT	3908	KUNING	RP. 95.000.000	SOLAR	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PIC AN BPK. ALDO 0812-8114-4125//KONDISI UNIT DEREK MESIN MATI, BAK HARUS REPAIR, KABIN REPAIRDOOR REPAIR (FR-L) , CARGO PANEL REPAIR (DECK) , HEADLIGHT (FR-L) , HEADLIGHT (FR-R) , FENDER REPAIR (FR-L) , FOG LAMP (L) , BUMPER REPAIR (FR) , DOOR REPAIR (FR-R) , ROOF REPAIR , FENDER REPAIR (FR-R) , FRONT PANEL REPLACE , FOG LAMP (R) , CARGO PANEL REPAIR (RR-L) , CARGO PANEL REPAIR (RR-R) , CARGO PANEL REPAIR (RR)DOOR TRIM (FR-L) , DOOR TRIM (FR-R) , INTERIOR SALOON , HEAD UNIT , CARSEAT (FR-L) , STEERING-WHEEL , DASHBOARD , CARSEAT (FR-R)FAN BELT , HEADER , ENGINE SERVICES (LIGHT) , WHEEL BEARING (RR) , TIRE (RR-L) IN , TIRE (RR-R) IN , DYNAMO STARTER , TIRE (FR-L) , TIRE (RR-R) OUT , RACK STEER , SPARK PLUG(S) , FUEL PUMP , COIL IGNITION , ENGINE SERVICES (HEAVY) , FUEL TANK REPAIR , SPRING (RR) , CEK ENGINE LIGHT , TIRE (RR-L) OUT , BATTERY , WHEEL BEARING (FR) , RADIATOR FAN , SPRING (FR) , CLUTCH PLATE , SHOCBREAKERS (FR) , POWER STEERING , BRAKE PAD (RR) , TIRE (FR-R) , INJECTOR , BRAKE PAD (FR) , DINAMO STARTER , TIRE (SPARE)// UNIT MENDAPAT CASHBACK 3.000.000																	
24	DE 8889 AG	MITSUBISHI COLT	2011	MT	3908	KUNING	RP. 101.000.000	SOLAR	0	E	E	E	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC KEVIN 081354149141// UNIT MENDAPAT CASHBACK 2.000.000																	
25	DH 1499 BF	HONDA MOBILIO	2016	MT	1496	HITAM MUTIARA	RP. 79.000.000	BENSIN	229751	D	E	D	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
* STNK TIDAK ADA * SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN KESESUAIAN UNIT DAN DOKUMEN UNIT * INSPEKSI PAK NATAN 081338280981 * PELUNASAN WAJIB DILAKUKAN MAKSIMAL H+2 SETELAH LELANG																	
26	DP 8613 HF	DAIHATSU GRANMAX	2019	MT	1298	SILVER METALIK	RP. 56.000.000	BENSIN	102776	D	D	E	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU//KOMPLEN MAKSIMAL SEBULAN SETELAH UNIT DIMENANGKAN// PIC DEDE 082194075310// UNIT MENDAPAT CASHBACK 1.500.000																	
27	DP 1451 LF	DAIHATSU SIGRA	2017	MT	1197	PUTIH	RP. 76.000.000	BENSIN	188270	C	C	C	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU//KOMPLEN MAKSIMAL SEBULAN SETELAH UNIT DIMENANGKAN // PIC DEDE 082194075310																	
28	DE 8565 LU	MITSUBISHI COLT	2017	MT	3908	KUNING	RP. 142.000.000	BENSIN	0	E	E	F	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU// PIC KEVIN 081354149141 // PLAT KUNING //																	
29	DP 1104 LE	TOYOTA AVANZA	2016	MT	1329	HITAM METALIK	RP. 112.000.000	BENSIN	152591	C	C	C	9 HARI KERJA	ADA 2024-03-30	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU//KOMPLAIN MAKSIMAL SEBULAN SETELAH UNIT DIMENANGKAN //PELUNASAN H+3 SETELAH LELANG //PIC RUDAL : 0853-9702-6168//																	
30	DE 1153 G	TOYOTA AVANZA 1.3G	2014	MT	1298	PUTIH	RP. 76.000.000	BENSIN	87299	D	D	E	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC KEVIN 081354149141																	
31	DC 8702 AU	SUZUKI CARRY CL PICK UP	2019	MT	1462	HITAM	RP. 56.000.000	BENSIN	49910	D	D	D	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC DEDE : +62 821-9407-5310// UNIT MENDAPAT CASHBACK 1.500.000																	
32	DB 1430 CP	NISSAN GRANDLIVINA XV	2008	MT	1498	ABU ABU METALIK	RP. 37.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT HARAP DI CEK DAHULU // UNIT TIDAK DICEKLIST OLEH TIM SMARTBID // UNIT BERADA DI POOL SLBG // PIC AN BPK. RUDOLF 0812-4270-3822 / EX NOPOL DB 4704 CD/ MESIN TIDAK BERFUNGSI, BODY TERGORES, ALARM TIDAK ADA, BUMPER DEPAN TIDAK ADA, LAMPU & SIGN DEPAN TIDAK ADA.DOOR REPAIR (TRUNK) MIRROR (R) WINDSHIELD WIPER FENDER REPAIR (RR-R) BUMPER REPAIR (RR) BUMPER REPLACE (FR) TAILLIGHT (RR-R) TAILLIGHT (RR-L) TURN LAMP (RR-L) GRILLES ENGINE HOOD REPAIR FENDER REPAIR (RR-L) FENDER REPAIR (FR-R) TURN LAMP (FR-L) HEADLIGHT (FR-L) EMBLEM TURN LAMP (RR-R) HEADLIGHT (FR-R) ROOF REPAIR FENDER REPAIR (FR-L) SIDE SKIRT REPAIR (R) MIRROR (L) SIDE SKIRT REPAIR (L) RIM COVER (RR-L) LICENSE PLATE TURN LAMP (FR-R)CARPET FLOOR (FR-L) CEILING TRIM HEAD UNIT CARPET FLOOR (FR-R) CARPET FLOOR (MID) TRUNK DOOR LOCK GEAR LEVER COVER CARPET FLOOR (RR) BOLT CRANE AND JACK TOOL KIT STEERING-WHEEL INTERIOR SALOON CARPETGASKET CYLINDER HEAD GASKET COVER HEAD COIL IGNITION INJECTOR TIRE (RR-R) TIRE (FR-R) RIM (SPARE) WHEEL BEARING (FR) SPRING (RR) FR-APRON TIRE (SPARE) CLUTCH BEARING RACK STEER TIRE (FR-L) L-APRON WHEEL BEARING (RR) SHOCBREAKERS (RR) R-APRON SHOCBREAKERS (FR) BRAKE MASTER CLUTCH PLATE BRAKE PAD (FR) REMOTE FAN BELT SPRING (FR) AIRCON EVAPORATOR ENGINE SERVICES (LIGHT) SPARK PLUG(S) BRAKE PAD (RR) BATTERY																	
33	DD 1262 NG	DAIHATSU SIGRA R	2018	MT	1197	HITAM	RP. 87.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT HARAP DI CEK DAHULU // UNIT TIDAK DICEKLIST OLEH TIM SMARTBID // PIC AN BPK ADI 0852-9971-7153/MESIN BERFUNGSI, BODY TERGORES, ALARM TIDAK ADA, SPARKBOARD TIDAK ADA.ENGINE HOOD REPAIR , DOOR REPAIR (TRUNK) , FR-DOOR GLASS (L) , RR-QUARTER GLASS (L) , RR-DOOR GLASS (L) , TAILLIGHT (RR-L) , TURN LAMP (RR-L) , DOOR REPAIR (RR-L) , BACK GLASS , ROOF REPAIR , ELECTRIC MIRROR (L) , FENDER REPAIR (RR-L) , RIM COVER (RR-R) , FOG LAMP (R) , FENDER REPAIR (FR-L) , SIDE SKIRT REPAIR (R) , ELECTRIC MIRROR (R) , RR-VENT GLASS (L) , DOOR REPAIR (FR-L) , FOG LAMP (L) , WINDSHIELD WIPER , RIM COVER (FR-L) , WINDSHIELD GLASS , SIDE SKIRT REPAIR (L) , BUMPER REPAIR (FR) , BUMPER REPAIR (RR)INTERIOR SALOON , TOOL KIT , CARPET , CARPET FLOOR (RR) , CARPET FLOOR (FR-L) , CARPET FLOOR (FR-R) , BOLT CRANE AND JACK , CARPET FLOOR (MID)CLUTCH PLATE , SPRING (FR) , SPRING (RR) , RIM (SPARE) , TIRE (FR-R) , TIRE (FR-L) , BRAKE PAD (RR) , TIRE (RR-R) , BRAKE PAD (FR) , BATTERY , L-APRON , WHEEL BEARING (RR) , ENGINE SERVICES (LIGHT) , SPARE KEY (IMMOBILIZER) , TIRE (RR-L) , FAN BELT , TIRE (SPARE) , WHEEL BEARING (FR) , FR-APRON , CLUTCH BEARING , SPARK PLUG(S) , R-APRON// UNIT MENDAPAT CASHBACK 3.000.000																	
34	B 1636 KZB	HONDA BRIO SATYADD11.2E	2013	MT	1198	ORANGE MUDA	RP. 79.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT HARAP DI CEK DAHULU // UNIT TIDAK DICEKLIST OLEH TIM SMARTBID // UNIT BERADA DI POOL SSRG // PIC AN BPK EDISON 0852-5454-4442//PINTU KANAN BELAKANG EX-REPAINT, WIPER BELAKANG T/A, HEAD UNIT GANTIAN, ACCU DROPPENDER REPAIR (FR-R) , BUMPER REPAIR (RR) , FENDER REPAIR (FR-L) , SIDE SKIRT REPAIR (L) , SIDE SKIRT REPAIR (R) , FENDER REPAIR (RR-L) , DOOR REPAIR (RR-R) , BUMPER REPAIR (FR)TOOL KIT , CARPET , INTERIOR SALOON , HEAD UNIT , BOLT CRANE AND JACKTIRE (SPARE) , ENGINE SERVICES (LIGHT) , WHEEL BEARING (FR) , SHOCBREAKERS (RR) , RACK STEER , FAN BELT , GASKET CYLINDER HEAD , SPRING (RR) , SPRING (FR) , SHOCBREAKERS (FR) , TIRE (FR-L) , BRAKE PAD (RR) , COIL IGNITION , GASKET COVER HEAD , TIRE (RR-L) , INJECTOR , WHEEL BEARING (RR) , TIRE (RR-R) , CLUTCH PLATE , SPARK PLUG(S) , TIRE (FR-R) , BRAKE PAD (FR)// UNIT MENDAPAT CASHBACK 3.000.000																	
35	DE 1451 AP	DAIHATSU AYLA	2020	MT	1197	ORANGE METALIK	RP. 100.000.000	BENSIN	82721	C	C	D	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC KEVIN 081354149141																	
36	DP 8270 HI	DAIHATSU GRANMAX PICK-UP	2021	MT	1298	HITAM	RP. 57.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT HARAP DI CEK DAHULU // UNIT TIDAK DICEKLIST OLEH TIM SMARTBID// PIC AN BPK ADI 0852-9971-7153//MESIN BERFUNGSI, BODY TERGORES, BAK BERKARAT & KEROPOSCARGO PANEL REPAIR (RR-L) , CARGO PANEL REPAIR (RR-R) , CARGO PANEL REPAIR (RR) , TURN LAMP (RR-R) , TURN LAMP (RR-L) , CARGO PANEL REPAIR (DECK) , FENDER REPAIR (FR-R) , RIM COVER (RR-L) , FENDER REPAIR (FR-L) , LICENSE PLAT , RIM COVER (FR-R) , TAILLIGHT (RR-L) , RIM COVER (FR-L) , TAILLIGHT (RR-R) , WINDSHIELD WIPER , RIM COVER (RR-R) , FRONT PANEL REPAIR , ROOF REPAIR , GRILLES , SIDE SKIRT REPAIR (R) , BUMPER REPLACE (FR) , SIDE SKIRT REPAIR (L)BOLT CRANE AND JACK , CARSEAT (FR-L) , HEAD UNIT , CARSEAT (FR-R) , CARPET , TOOL KIT , STEERING-WHEEL , INTERIOR SALOON , SUNVISOR (L)WHEEL BEARING (RR) , RACK STEER , WHEEL BEARING (FR) , RIM (SPARE) , AIR FILTER , TIRE (RR-L) , L-APRON , TIRE (RR-R) , ENGINE SERVICES (LIGHT) , TIRE (FR-L) , TIRE (FR-R) , TIRE (SPARE) , BRAKE PAD (RR) , SPRING (RR) , SPRING (FR) , BATTERY , FAN BELT , CLUTCH PLATE , R-APRON , MUFFLER , BRAKE PAD (FR) , SPARK PLUG(S)// UNIT MENDAPAT CASHBACK 1.500.000																	
[DICETAK TGL. 08-09-2024]	TOYOTA AVANZA	2010	MT	2495	ABU ABU METALIK	RP. 44.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A	
														KEUR T/A	SPH T/A	FORM A T/A	

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
KEUR T/A	SPH T/A	FORM A T/A	SEBELUM MELAKUKAN PENAWARAN UNIT HARAP DI CEK DAHULU // UNIT TIDAK DICEKLIST OLEH TIM SMARTBID // PIC AN BPK. NANDO 0852-7005-0894// COPY FAKTUR TA //KONDISI UNIT MESIN MATI, MESIN RUSAK.RIM COVER (FR-L) ENGINE HOOD REPLACE ROOF REPAIR BUMPER REPAIR (RR) FOG LAMP (L) FOG LAMP (R) DOOR REPAIR (TRUNK) DOOR REPAIR (FR-L) BUMPER REPAIR (FR) DOOR REPAIR (FR-R) DOOR REPAIR (RR-L) RIM COVER (RR-R) DOOR REPAIR (RR-R) CARSEAT (RR-L) CARSEAT (RR-R) GEAR LEVER COVER HEAD UNIT TOOL KIT INTERIOR SALOON BOLT CRANE AND JACKPOWER STEERING ENGINE MOUNTING DISC PAD BRAKE MASTER WHEEL BEARING (FR) WHEEL BEARING (RR) CHECK ENGINE INDIKATOR CLUTCH BEARING DYNAMO STARTER SHOCBREAKERS (FR) TIRE (RR-L) SPRING (RR) HEADER CLUTCH PLATE SPRING (FR) SHOCBREAKERS (RR) INJECTOR TIRE (SPARE) TIRE (FR-R) RACK STEER WHEEL AXELS (RR) ENGINE SERVICES (HEAVY) TIRE (RR-R) BATTERY TIRE (FR-L) SPARK PLUG(S) GASKET COVER HEAD COIL IGNITION FAN BELT RADIATOR FAN AIRCON EVAPORATOR GASKET CYLINDER HEAD BRAKE PAD (FR) BRAKE PAD (RR) RADIATOR WHEEL AXELS (FR)// UNIT MENDAPAT CAHSBACK 3.000.000														
38	DT 1707 JB	TOYOTA AVANZA 1.3E	2016	MT	1329	MERAH	RP. 76.000.000	BENSIN	916655	D	C	C	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //PIC MIFTAH 082196768826//																	
39	DC 1254 GW	HONDA BRIO	2016	MT	1198	HITAM MUTIARA	RP. 88.000.000	BENSIN	106223	C	C	C	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU//KOMPLEN MAKSIMAL SEBULAN SETELAH UNIT DIMENANGKAN //PELUNASAN H+3 SETELAH LELANG// PIC DEDE 082194075310																	
40	DD 1949 QD	TOYOTA INNOVA	2012	MT	1998	HITAM METALIK	RP. 69.000.000	BENSIN	0	D	D	E	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU//KOMPLAIN MAKSIMAL SEBULAN SETELAH UNIT DIMENANGKAN //PELUNASAN H+3 SETELAH LELANG //PIC RUDAL : 0853-9702-6168//																	
41	DN 1325 AM	TOYOTA AVANZA 1.5G	2013	MT	1495	PUTIH	RP. 81.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI TOLITOLI CAB. TOLI-TOLI - JL. BANGAU - KEL. TULLUWEY - KEC. BAOLAN, TOLITOLI // MESIN BERFUNGSI, BODY TERGORES, ALARM TIDAK ADA, MESIN REMBES OLI.BUMPER REPAIR (RR) , EMBLEM , RIM COVER (FR-L) , DOOR REPAIR (TRUNK) , ENGINE HOOD REPAIR , RIM COVER (RR-R) , RIM COVER (RR-L) , FENDER REPAIR (FR-L) , ROOF REPAIR , RIM COVER (FR-R) , FENDER REPAIR (FR-R) , MIRROR (R) , HEADLIGHT (FR-L) , HEADLIGHT (FR-R) , TURN LAMP (FR-L) , MIRROR (L) , SIDE SKIRT REPAIR (R) , BUMPER REPLACE (FR) , WINDSHIELD WIPER , TURN LAMP (FR-R) , SIDE SKIRT REPAIR (L)CARPET FLOOR (MID) , HEAD UNIT , CARPET , CARPET FLOOR (FR-L) , CARPET FLOOR (RR) , CARPET FLOOR (FR-R) , DOOR TRIM (TRUNK) , CEILING TRIM , SEATBELT (RR-L) , INTERIOR SALOON , SEATBELT (RR-R) , TOOL KIT , BOLT CRANE AND JACK , STEERING-WHEELTIRE (FR-R) , AIRBAG , AIRBAG SENSOR , RIM (SPARE) , ENGINE SERVICES (LIGHT) , WHEEL BEARING (RR) , GASKET COVER HEAD , BRAKE MASTER , TIRE (RR-L) , GASKET CYLINDER HEAD , CLUTCH PLATE , TIRE (FR-L) , SHOCBREAKERS (RR) , RADIATOR , TIRE (SPARE) , BATTERY , SPRING (FR) , BRAKE PAD (RR) , SHOCBREAKERS (FR) , AIRCON EVAPORATOR , REMOTE , RADIATOR FAN , WHEEL BEARING (FR) , TIRE (RR-R) , FAN BELT , SPRING (RR) , RACK STEER , CLUTCH BEARING , BRAKE PAD (FR) , SPARK PLUG(S)// UNIT MENDAPAT CASHBACK 3.000.000																	
42	DD 8829 SJ	DAIHATSU GRANMAX PICK-UP	2021	MT	1495	PUTIH	RP. 76.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI LUWU TIMUR POOL CAB.MANGKUTANA, DUSUN SINTUWU, KEL. MALEKU, KEC. MANGKUTANA, KAB. LUWU TIMUR // MESIN BERFUNGSI, BODY TERGORES, BAK BARET & AGAK BERKARAT.CARGO PANEL REPAIR (RR-R) , CARGO PANEL REPAIR (RR-L) , RIM COVER (RR-L) , TURN LAMP (FR-R) , DOOR REPAIR (FR-R) , RIM COVER (FR-L) , WINDSHIELD WIPER , FENDER REPAIR (FR-L) , FENDER REPAIR (FR-R) , MIRROR (R) , TURN LAMP (FR-L) , RIM COVER (FR-R) , ROOF REPAIR , SIDE SKIRT REPAIR (L) , MIRROR (L) , RIM COVER (RR-R) , CARGO PANEL REPAIR (DECK) , HEADLIGHT (FR-L) , HEADLIGHT (FR-R) , SIDE SKIRT REPAIR (R) , LICENSE PLAT , BUMPER REPLACE (FR) , CARGO PANEL REPAIR (RR)CARPET , BOLT CRANE AND JACK , TOOL KIT , SUNVISOR (L) , INTERIOR SALOON , HEAD UNITGASKET COVER HEAD , GASKET CYLINDER HEAD , BRAKE PAD (FR) , SHOCBREAKERS (FR) , CLUTCH PLATE , SHOCBREAKERS (RR) , RIM (SPARE) , AIR FILTER , FAN BELT , BRAKE PAD (RR) , SPRING (FR) , SPRING (RR) , TIRE (SPARE) , TIRE (RR-R) , TIRE (RR-L) , SPARK PLUG(S) , ENGINE SERVICES (LIGHT) , TIRE (FR-L) , TIRE (FR-R) , BATTERY// UNIT MENDAPAT CASHBACK 3.000.000																	
43	DM 8637 B	HINO DUTRO 130HD	2012	MT	-	HIJAU	RP. 0	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI TOLITOLI CAB. TOLI-TOLI - JL. BANGAU - KEL. TULLUWEY - KEC. BAOLAN, TOLITOLI // MESIN BERFUNGSI, BODY BARET & REKONDISI CAT ULANG, MESIN REMBES OLI.TURN LAMP (RR-R) , CARGO PANEL REPAIR (RR-R) , CARGO PANEL REPAIR (RR) , TURN LAMP (RR-L) , DOOR REPAIR (FR-R) , SIDE SKIRT REPAIR (R) , CARGO PANEL REPAIR (RR-L) , SIDE SKIRT REPAIR (L) , TAILLIGHT (RR-L) , DOOR REPAIR (FR-L) , LICENSE PLAT , CARGO PANEL REPAIR (DECK) , TAILLIGHT (RR-R) , FOG LAMP (L) , FOG LAMP (R) , WINDSHIELD WIPER , MIRROR (R) , RIM COVER (RR-L) , RIM COVER (FR-L) , RIM COVER (RR-R) , MIRROR (L) , RIM COVER (FR-R) , ROOF REPAIR , FRONT PANEL REPAIR , BUMPER REPLACE (FR)SEATBELT (FR-R) , SEATBELT (FR-L) , INTERIOR SALOON , HEAD UNIT , BOLT CRANE AND JACK , CARPET , TOOL KIT , STEERING-WHEEL , GEAR LEVER COVERTIRE (RR-R) OUT , AIR FILTER , ENGINE SERVICES (LIGHT) , SPRING (FR) , SPRING (RR) , TIRE (SPARE) , WHEEL BEARING (FR) , TIRE (RR-L) OUT , TIRE (RR-R) IN , BRAKE PAD (RR) , BRAKE MASTER , FAN BELT , CLUTCH PLATE , SHOCBREAKERS (FR) , TIRE (FR-L) , BRAKE PAD (FR) , TIRE (RR-L) IN , TIRE (FR-R) , SPARK PLUG(S) , WHEEL BEARING (RR) , SHOCBREAKERS (RR) , RACK STEER , BATTERY																	
44	PA 1983 KB	TOYOTA INNOVA G	2012	MT	1998	SILVER METALIK	RP. 99.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN			
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI NABIRE CAB. NABIRE GANG MAWAR RT/RW 04/02 KEL BUMIWONOREJO KEC NABIRE KAB NABIRE //ENGINE HOOD REPAIR , DOOR REPAIR (RR-R) , FENDER REPAIR (FR-R) , DOOR REPAIR (FR-R) , DOOR REPAIR (RR-L) , BACK GLASS , FENDER REPAIR (FR-L) , DOOR REPAIR (FR-R) , BUMPER REPAIR (RR) , DOOR REPAIR (TRUNK) , BUMPER REPAIR (FR) , DOOR REPAIR (FR-L)CARSEAT (FR-R) , TOOL KIT , BOLT CRANE AND JACK , INTERIOR SALOON , CARSEAT (FR-L) , HEAD UNITBRAKE PAD (RR) , TIRE (FR-R) , AIRCON EVAPORATOR , RADIATOR FAN , TIRE (RR-L) , CLUTCH BEARING , HEADER , GASKET CYLINDER HEAD , ENGINE SERVICES (HEAVY) , CLUTCH PLATE , GASKET COVER HEAD , SPRING (FR) , SHOCBREAKERS (FR) , COIL IGNITION , BATTERY , FAN BELT , TIRE (SPARE) , SHOCBREAKERS (RR) , SPARK PLUG(S) , INJECTOR , TIRE (RR-R) , SPRING (RR) , RADIATOR , WHEEL AXELS (RR) , BRAKE PAD (FR) , WHEEL AXELS (FR) , TIRE (FR-L)// UNIT MENDAPAT CASHBACK 3.000.000																		
45	PB 1646 T	TOYOTA RUSH S	2012	MT	1495	SILVER METALIK	RP. 82.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A	
															KEUR T/A	SPH T/A	FORM A T/A	
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI SORONG CAB. SORONG JL. SAPTA TARUNA KM 10 KEL.SAWAGUMU SORONG PAPUA // HEADLIGHT (FR-L) , BUMPER REPAIR (RR) , TURN LAMP (FR-R) , DOOR REPAIR (RR-L) , FOG LAMP (R) , BUMPER REPAIR (FR) , DOOR REPAIR (FR-L) , DOOR REPAIR (FR-R) , DOOR REPAIR (TRUNK) , ROOF REPAIR , HEADLIGHT (FR-R) , TURN LAMP (FR-L) , DOOR REPAIR (RR-R) , FOG LAMP (L)CARSEAT (FR-L) , INTERIOR SALOON , CARSEAT (FR-R) , TOOL KIT , BOLT CRANE AND JACK , HEAD UNITCLUTCH PLATE , RIM (RR-R) , RIM (RR-L) , TIRE (FR-R) , BRAKE PAD (RR) , AIRCON EVAPORATOR , BATTERY , RIM (SPARE) , WHEEL AXELS (FR) , TIRE (RR-L) , TIRE (SPARE) , RACK STEER , WHEEL AXELS (RR) , TIRE (RR-R) , TIRE (FR-L) , SHOCBREAKERS (FR) , RIM (FR-R) , GASKET COVER HEAD , RIM (FR-L) , COIL IGNITION , GASKET CYLINDER HEAD , ENGINE SERVICES (HEAVY) , MUFFLER , RADIATOR FAN , CLUTCH BEARING , SPRING (RR) , FAN BELT , SPRING (FR) , BRAKE PAD (FR) , SHOCBREAKERS (RR) , HEADER , SPARK PLUG(S)//UNIT MENDAPAT CASHBACK 3.000.000																		
46	DG 1116 T	TOYOTA INNOVA G	2011	MT	1998	HITAM METALIK	RP. 67.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A	
															KEUR T/A	SPH T/A	FORM A T/A	
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI TERNATE CAB. TERNATE, LORONG JERUK RT/RW 007/002 KEL UBO-UBO KEC TERNATE SELATAN KOTA TERNATE MALUKU UTARA // UNIT EX TAKSI ANTAR KABUPATEN. UNIT EX LAKA APRON DEPAN PATAHWINDSHIELD WIPER , RIM COVER (RR-R) , TURN LAMP (RR-R) , RIM COVER (FR-L) , TURN LAMP (FR-L) , FOG LAMP (L) , DOOR REPAIR (RR-R) , DOOR REPAIR (TRUNK) , EMBLEM , FOG LAMP (R) , FENDER REPAIR (FR-L) , HEADLIGHT (FR-L) , EX-ACCIDENT , ENGINE HOOD REPAIR , HEADLIGHT (FR-R) , RIM COVER (FR-R) , TURN LAMP (RR-L) , TURN LAMP (FR-R) , TAILLIGHT (RR-R) , BUMPER REPAIR (RR) , DOOR REPAIR (RR-L) , BUMPER REPAIR (FR) , DOOR REPAIR (FR-R) , TAILLIGHT (RR-L) , FENDER REPAIR (FR-R)HEADREST (RR-L) , CARPET FLOOR (FR-L) , CARPET , HEAD UNIT , INTERIOR SALOON , HEADREST (RR-R) , HEADREST (FR-L) , DASHBOARD , HEADREST (M-R) , CARPET FLOOR (FR-R) , TOOL KIT , CARSEAT (FR-L) , CARSEAT (FR-R) , HEADREST (FR-R) , HEADREST (M-L) , BOLT CRANE AND JACKGASKET CYLINDER HEAD , TIRE (RR-L) , TIRE (FR-L) , COIL IGNITION , RADIATOR FAN , TIRE (RR-R) , ENGINE SERVICES (HEAVY) , HEADER , WHEEL AXELS (RR) , INJECTOR , BATTERY , TIRE (FR-R) , BRAKE PAD (RR) , SPRING (RR) , CLUTCH BEARING , GASKET COVER HEAD , BRAKE PAD (FR) , WHEEL BEARING (RR) , WHEEL BEARING (FR) , TIRE (SPARE) , L-APRON , RADIATOR , SHOCBREAKERS (RR) , ENGINE MOUNTING , SPARK PLUG(S) , SHOCBREAKERS (FR) , WHEEL AXELS (FR) , SPRING (FR) , FAN BELT , CLUTCH PLATE																		
47	DD 1162 MZ	TOYOTA AVANZA 1.3E	2014	MT	1298	PUTIH	RP. 51.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A	
															KEUR T/A	SPH T/A	FORM A T/A	
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI SENGKANG CAB. SENGKANG, DESA MADUKELLENG, JL. MERPATI, KEL. MADUKELLENG, KEC. TEMPE, KAB. WAJO // MESIN TIDAK BERFUNGSI, SPARKBOARD TIDAK ADA, BODY BARET & SEBAGIAN PENYOK, UNIT INDIKASI EKS LAKA LANTAS.RR-QUARTER GLASS (R) , DOOR REPAIR (RR-L) , RR-QUARTER GLASS (L) , ROOF REPAIR , ENGINE HOOD REPAIR , FENDER REPAIR (FR-L) , RIM COVER (FR-L) , TURN LAMP (FR-R) , FOG LAMP (L) , BUMPER REPLACE (RR) , BACK GLASS , SIDE SKIRT REPAIR (L) , DOOR REPAIR (TRUNK) , DOOR REPAIR (RR-R) , RIM COVER (RR-R) , WINDSHIELD WIPER , RIM COVER (RR-L) , GRILLES , FENDER REPAIR (FR-R) , TAILLIGHT (RR-R) , FOG LAMP (R) , EMBLEM , SIDE SKIRT REPAIR (R) , TURN LAMP (FR-L) , MIRROR (L) , ELECTRIC MIRROR (R) , HEADLIGHT (FR-R) , RIM COVER (FR-R) , BUMPER REPLACE (FR) , HEADLIGHT (FR-L)CARSEAT (RR-R) , CARSEAT (RR-L) , HEADREST (RR-R) , HEADREST (FR-L) , CARPET , BOLT CRANE AND JACK , TOOL KIT , CEILING LAMP (RR) , HEADREST (RR-L) , SEATBELT (RR-L) , CEILING TRIM , HEADREST (FR-R) , HEADREST (M-L) , CARPET FLOOR (RR) , CARPET FLOOR (FR-R) , INTERIOR SALOON , SEATBELT (FR-R) , CARPET FLOOR (FR-L) , HORN , HEAD UNIT , STEERING-WHEELAIRBAG SENSOR , RACK STEER , WHEEL BEARING (FR) , COIL IGNITION , WHEEL BEARING (RR) , GASKET COVER HEAD , REMOTE , GASKET CYLINDER HEAD , KEY (NO IMMOBILIZER) , AIRBAG , ENGINE SERVICES (HEAVY) , SPRING (RR) , RIM (FR-R) , BRAKE PAD (FR) , SHOCBREAKERS (RR) , SHOCBREAKERS (FR) , SPRING (FR) , CLUTCH BEARING , TIRE (SPARE) , RIM (RR-R) , TIRE (FR-R) , RIM (RR-L) , TIRE (FR-L) , TIRE (RR-R) , AIRCON EVAPORATOR , BRAKE PAD (RR) , SPARK PLUG(S) , BRAKE MASTER , FAN BELT , RIM (SPARE) , RIM (FR-L) , TIRE (RR-L) , BATTERY // ADA PERBEDAAN WARNA PADA FISIK HITAM PUTIH PADA DOKUMEN PUTIH// UNIT MENDAPAT CASHBACK 3.000.000																		
48	DN 8196 RY	SUZUKI CARRY PU	2020	MT	1462	HITAM	RP. 77.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A	
															KEUR T/A	SPH T/A	FORM A T/A	
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI LUWUK BANGGAI CAB. LUWUK BANGGAI, JALAN TRANS SULAWESI, KOYOAN PERMAI // MESIN BERFUNGSI, BODY TERGORES, BAK BARET.CARGO PANEL REPAIR (RR) , RIM COVER (FR-R) , CARGO PANEL REPAIR (DECK) , DOOR REPAIR (FR-L) , SIDE SKIRT REPAIR (R) , TAILLIGHT (RR-R) , DOOR REPAIR (FR-R) , TURN LAMP (RR-R) , SIDE SKIRT REPAIR (L) , BUMPER REPAIR (FR)SUNVISOR (L) , TOOL KIT , CARPET , INTERIOR SALOON , BOLT CRANE AND JACKCLUTCH PLATE , WHEEL BEARING (FR) , SHOCBREAKERS (FR) , WHEEL BEARING (RR) , SHOCBREAKERS (RR) , RIM (SPARE) , TIRE (RR-R) , SPRING (FR) , TIRE (SPARE) , SPRING (RR) , AIR FILTER , FAN BELT , BATTERY , ENGINE SERVICES (LIGHT) , TIRE (FR-L) , TIRE (RR-L) , TIRE (FR-R) , BRAKE PAD (FR) , BRAKE PAD (RR) , SPARK PLUG(S)// UNIT MENDAPATCASHBACK 3.000.000																		
49	DN 1112 GY	TOYOTA AVANZA 1.3G	2013	MT	1298	ABU ABU METALIK	RP. 57.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A	
															KEUR T/A	SPH T/A	FORM A T/A	
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI MOROWALI CAB. MOROWALI, BUNGI, BUNGKI TENGAH, MOROWALI, SULAWESI TENGAH // MESIN BERFUNGSI, ALARM TIDAK ADA, MESIN PINCANG & KASAR.TURN LAMP (FR-L) , RIM COVER (FR-R) , RIM COVER (FR-R) , ROOF REPAIR , HEADLIGHT (FR-R) , DOOR REPAIR (RR-L) , TURN LAMP (FR-R) , HEADLIGHT (FR-L) , SIDE SKIRT REPLACE (L) , TAILLIGHT (RR-R) , FENDER REPAIR (RR-L) , ENGINE HOOD REPAIR , FENDER REPAIR (RR-R) , ANTENNA , SIDE SKIRT REPAIR (R) , TAILLIGHT (RR-L) , DOOR REPAIR (FR-L) , TURN LAMP (RR-R) , FENDER REPAIR (FR-L) , RIM COVER (FR-L) , DOOR REPAIR (RR-R) , FENDER REPAIR (FR-R) , GRILLES , FOG LAMP (R) , DOOR REPAIR (FR-R) , FOG LAMP (L) , MIRROR (R) , BUMPER REPLACE (RR) , DOOR REPAIR (TRUNK) , TURN LAMP (RR-L) , MIRROR (L) , RR-QUARTER GLASS (R) , RR-QUARTER GLASS (L) , EMBLEM , LICENSE PLATE , WINDSHIELD WIPER , RIM COVER (RR-R) , BUMPER REPLACE (FR)INTERIOR SALOON , HEADREST (FR-L) , CONSOLE BOX , CARPET FLOOR (FR-R) , HEADREST (RR-R) , CARPET FLOOR (FR-L) , HEADREST (M-R) , CARPET FLOOR (MID) , SEATBELT (RR-R) , CARPET FLOOR (RR) , POWER-WINDOW PANEL (RR-L) , BOLT CRANE AND JACK , TOOL KIT , POWER-WINDOW PANEL (DRV) , CENTRAL LOCK , CARSEAT (RR-R) , POWER-WINDOW PANEL (RR) , SEATBELT (RR-L) , HEADREST (M-L) , CARSEAT (M-L) , HEADREST (RR-L) , CARSEAT (RR-L) , CARSEAT (M-R) , HEAD UNIT , DOOR TRIM (TRUNK) , DOOR TRIM (FR-R) , CARPET , DOOR TRIM (RR-R) , CARSEAT (FR-L) , DOOR TRIM (RR-L)DYNAMO STARTER , CHECK ENGINE INDIKATOR , GASKET CYLINDER HEAD , SPRING (RR) , SPRING (FR) , COIL IGNITION , RIM (SPARE) , GASKET COVER HEAD , TIRE (RR-L) , ENGINE SERVICES (HEAVY) , RIM (FR-L) , RIM (RR-L) , RIM (FR-R) , CLUTCH BEARING , RIM (RR-R) , TIRE (FR-R) , WHEEL BEARING (RR) , TIRE (SPARE) , TIRE (RR-R) , REMOTE , WHEEL BEARING (FR) , TIRE (FR-L) , FAN BELT , SPARK PLUG(S) , MUFFLER , BATTERY , CLUTCH PLATE , BRAKE MASTER , INJECTOR , SHOCBREAKERS (RR) , BRAKE PAD (FR) , AIRCON EVAPORATOR , RADIATOR FAN , SHOCBREAKERS (FR) , RACK STEER , BRAKE PAD (RR) , RADIATOR// UNIT MENDAPAT CASHBACK 3.000.000																		
[DICETAK TGL. 08-09-2024]			TOYOTA HILUX DOUBLECABIN	2016	MT	2494	PUTIH	RP. 202.000.000	SOLAR	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
KEUR T/A	SPH T/A	FORM A T/A	UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI MOROWALI CAB. MOROWALI, BUNGI, BUNGKI TENGAH, MOROWALI, SULAWESI TENGAH // MESIN TIDAK BERFUNGSI, ALARM TIDAK ADA, BODY TERGORES, BAK BARET & PENYOK.TURN LAMP (RR-R), TAILLIGHT (RR-L), LICENSE PLAT, CARGO PANEL REPAIR (DECK), CARGO PANEL REPAIR (RR), ENGINE HOOD REPAIR, ROOF REPAIR, SIDE SKIRT REPAIR (R), CARGO PANEL REPAIR (RR-R), TAILLIGHT (RR-R), TURN LAMP (RR-L), DOOR REPAIR (RR-R), SIDE SKIRT REPAIR (L), FENDER REPAIR (FR-R), CARGO PANEL REPAIR (RR-L), WINDSHIELD WIPER, RIM COVER (RR-L), RIM COVER (FR-R), RIM COVER (RR-R), RIM COVER (FR-L), FOG LAMP (R), TURN LAMP (FR-R), FOG LAMP (L), MIRROR (R), BUMPER REPAIR (FR), MIRROR (L), HEADLIGHT (FR-L), HEADLIGHT (FR-R), TURN LAMP (FR-L)CEILING TRIM, TOOL KIT, INTERIOR SALOON, BOLT CRANE AND JACK, HEAD UNIT, CARPETSRING (FR), RIM (FR-R), FUEL PUMP, RIM (SPARE), SPRING (RR), TIRE (RR-L), RIM (RR-R), GASKET CYLINDER HEAD, GASKET COVER HEAD, COIL IGNITION, TIRE (SPARE), RIM (FR-L), RIM (RR-L), AIR FILTER, TIRE (FR-L), TIRE (FR-R), FAN BELT, SPARE KEY (IMMOBILIZER), REMOTE, TIRE (RR-R), WHEEL BEARING (FR), ENGINE SERVICES (LIGHT), SHOCBREAKERS (RR), WHEEL BEARING (RR), BRAKE MASTER, SPARK PLUG(S), RADIATOR FAN, BRAKE PAD (FR), CLUTCH PLATE, SHOCBREAKERS (FR), BRAKE PAD (RR), RADIATOR, INJECTOR, AIRCON EVAPORATOR, BATTERY// PIC AN BPK FERDY 0822-4916-6365														
51	DN 1648 MF	TOYOTA INNOVA	2006	MT	1998	HITAM METALIK	RP. 44.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI TOLI-TOLI CAB. TOLI-TOLI, JL. BANGAU, KEL. TULUWEY, KEC. BAOLAN, TOLITOLI // MESIN BERFUNGSI, BODY BARET.FENDER REPAIR (RR-L), DOOR REPAIR (RR-R), TURN LAMP (RR-R), FENDER REPAIR (RR-R), BUMPER REPAIR (RR), TAILLIGHT (RR-R), HEADLIGHT (FR-L), TURN LAMP (FR-R), FOG LAMP (L), FENDER REPAIR (FR-L), FOG LAMP (R), SIDE SKIRT REPLACE (L), FENDER REPAIR (FR-R), TURN LAMP (RR-L), WINDSHIELD WIPER, HEADLIGHT (FR-R), TURN LAMP (FR-L), TAILLIGHT (RR-L), RIM COVER (FR-L), DOOR REPAIR (FR-L), RIM COVER (RR-L), DOOR REPAIR (RR-L), RIM COVER (FR-R), DOOR REPAIR (FR-R), EMBLEM, ENGINE HOOD REPAIR, ROOF REPAIR, MIRROR (R), RIM COVER (RR-R), MIRROR (L), SIDE SKIRT REPAIR (R), DOOR REPAIR (TRUNK), BUMPER REPLACE (FR)TOOL KIT, CARPET FLOOR (MID), CARPET FLOOR (RR), DASHBOARD, CARPET FLOOR (FR-L), BOLT CRANE AND JACK, CARPET, CARPET FLOOR (FR-R), HEAD UNIT, INTERIOR SALOON, CEILING TRIMENGINE SERVICES (HEAVY), COIL IGNITION, RIM (RR-L), RIM (RR-R), RIM (FR-L), ENGINE MOUNTING, RIM (FR-R), RADIATOR, WHEEL BEARING (FR), GASKET COVER HEAD, CLUTCH BEARING, TIRE (FR-L), INJECTOR, SPRING (FR), BRAKE MASTER, GASKET CYLINDER HEAD, FAN BELT, SPRING (RR), CLUTCH PLATE, RIM (SPARE), TIRE (SPARE), RADIATOR FAN, TIRE (RR-L), BRAKE PAD (FR), BRAKE PAD (RR), WHEEL BEARING (RR), TIRE (FR-R), SHOCBREAKERS (RR), RACK STEER, SHOCBREAKERS (FR), TIRE (RR-R), SPARK PLUG(S), BATTERY, AIRCON EVAPORATOR, REMOTE // NOKA BERKARAT KOROSI MULAI 6 DIGIT TIDAK KEBACA// UNIT MENDAPAT CASHBACK 3.000.000																	
52	DD 8993 XP	DAIHATSU GRANMAX PICK-UP	2013	MT	1298	HITAM	RP. 32.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI LUWU TIMUR CAB. MANGKUTANA, DUSUN SINTUWU, KEL. MALEKU, KEC. MANGKUTANA, KAB. LUWU TIMUR // MESIN TIDAK BERFUNGSI, UNIT LAKA LANTAS, BODY BARET & PENYOK.FR-DOOR GLASS (L), FR-DOOR GLASS (R), ANTENNA, ROOF REPLACE, TURN LAMP (RR-R), DOOR REPAIR (FR-R), CARGO PANEL REPAIR (RR-L), WINDSHIELD WIPER, CARGO PANEL REPAIR (DECK), TURN LAMP (FR-L), CABIN REPAIR, CARGO PANEL REPAIR (RR), CARGO PANEL REPAIR (RR-R), TAILLIGHT (RR-R), EMBLEM, DOOR REPAIR (FR-L), RIM COVER (RR-R), SIDE SKIRT REPAIR (L), TAILLIGHT (RR-L), SIDE SKIRT REPLACE (R), TURN LAMP (FR-R), TURN LAMP (RR-L), LICENSE PLAT, RIM COVER (FR-L), WINDSHIELD GLASS, FENDER REPLACE (FR-R), FRONT PANEL REPLACE, HEADLIGHT (FR-R), GRILLES, RIM COVER (FR-R), MIRROR (R), RIM COVER (RR-L), FENDER REPLACE (FR-L), HEADLIGHT (FR-L), BUMPER REPLACE (FR), MIRROR (L)BOLT CRANE AND JACK, CEILING TRIM, DASHBOARD, CARPET, DOOR TRIM (FR-L), SUNVISOR (L), HEAD UNIT, REAR VIEW MIRROR, DOOR TRIM (FR-R), CARSEAT (FR-R), INTERIOR SALOON, TOOL KITINJECTOR, RIM (RR-L), RIM (RR-R), SPRING (FR), RIM (FR-L), SHOCBREAKERS (RR), TIRE (SPARE), ECU, BRAKE PAD (FR), RIM (FR-R), GASKET CYLINDER HEAD, RADIATOR, TIRE (FR-R), GASKET COVER HEAD, COIL IGNITION, L-APRON, RIM (SPARE), RADIATOR FAN, BRAKE MASTER, BRAKE PAD (RR), SHOCBREAKERS (FR), R-APRON, TIRE (RR-L), WHEEL BEARING (RR), SPRING (RR), SPARK PLUG(S), TIRE (FR-L), RACK STEER, FR-APRON, AIR FILTER, FAN BELT, ENGINE SERVICES (HEAVY), BATTERY, WHEEL BEARING (FR)// UNIT MENDAPAT CASHBACK 1.500.000																	
53	DD 1094 XO	DAIHATSU XENIA	2012	MT	-	PUTIH	RP. 0	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI LUWU TIMUR CAB. MANGKUTANA, DUSUN SINTUWU, KEL. MALEKU, KEC. MANGKUTANA, KAB. LUWU TIMUR // MESIN TIDAK BERFUNGSI, BODY TERGORES, ALARM TIDAK ADA, UNIT LAKA LANTAS, MESIN REMBES OLI, INDIKASI NOSIN KETRIKAN ULANG.FR-DOOR GLASS (L), WINDSHIELD GLASS, EX-ACCIDENT, BUMPER REPLACE (RR), TURN LAMP (FR-L), DOOR REPAIR (TRUNK), TURN LAMP (RR-R), MIRROR (R), FENDER REPAIR (FR-R), ROOF REPAIR, EMBLEM, GRILLES, TAILLIGHT (RR-R), LICENSE PLATE, SIDE SKIRT REPAIR (R), HEADLIGHT (FR-L), FENDER REPAIR (FR-L), RIM COVER (FR-L), WINDSHIELD WIPER, TURN LAMP (FR-R), SIDE SKIRT REPAIR (L), BUMPER REPLACE (FR), MIRROR (L), FOG LAMP (L), RIM COVER (FR-R), ENGINE HOOD REPAIR, FOG LAMP (R), HEADLIGHT (FR-R)CEILING LAMP (FR), CARSEAT (M-L), CARPET FLOOR (MID), CARPET FLOOR (RR), CARPET FLOOR (FR-R), INTERIOR MIRROR, CARPET FLOOR (FR-L), BOLT CRANE AND JACK, INTERIOR SALOON, CARPET, CEILING TRIM, TOOL KIT, HEAD UNITINJECTOR, CHASSIS, RACK STEER, POWER STEERING, CLUTCH PLATE, SHOCBREAKERS (FR), FAN BELT, WHEEL BEARING (RR), AIRCON EVAPORATOR, ENGINE SERVICES (LIGHT), RADIATOR FAN, SHOCBREAKERS (RR), RADIATOR, WHEEL BEARING (FR), REMOTE, CLUTCH BEARING, BRAKE MASTER, COIL IGNITION, L-APRON, TIRE (FR-R), TIRE (SPARE), RIM (FR-R), GASKET CYLINDER HEAD, TIRE (RR-L), TIRE (FR-L), R-APRON, SPRING (FR), BRAKE PAD (FR), SPARK PLUG(S), GASKET COVER HEAD, TIRE (RR-R), SPRING (RR), BRAKE PAD (RR), BATTERY, FR-APRON																	
54	DP 8556 GK	SUZUKI CARRY PU	2021	MT	1462	PUTIH	RP. 67.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI LUWU TIMUR CAB. MANGKUTANA, DUSUN SINTUWU, KEL. MALEKU, KEC. MANGKUTANA, KAB. LUWU TIMUR // MESIN BERFUNGSI, BODY TERGORES, BAK BARET & PENYOK.DOOR REPAIR (FR-R), TAILLIGHT (RR-L), TURN LAMP (RR-L), MIRROR (L), EMBLEM, WINDSHIELD WIPER, CARGO PANEL REPAIR (DECK), CARGO PANEL REPAIR (R), RIM COVER (FR-L), RIM COVER (RR-L), ROOF REPAIR, SIDE SKIRT REPAIR (L), MIRROR (R), RIM COVER (FR-R), FRONT PANEL REPAIR, GRILLES, BUMPER REPLACE (FR)CARPET, SUNVISOR (L), INTERIOR SALOON, TOOL KIT, HEAD UNIT, BOLT CRANE AND JACKTIRE (FR-L), SPRING (RR), WHEEL BEARING (FR), BRAKE PAD (RR), ENGINE SERVICES (LIGHT), AIR FILTER, TIRE (FR-R), FAN BELT, SHOCBREAKERS (FR), SHOCBREAKERS (RR), SPRING (FR), RIM (SPARE), BRAKE PAD (FR), TIRE (RR-R), CLUTCH PLATE, TIRE (SPARE), BATTERY, TIRE (RR-L), WHEEL BEARING (RR), SPARK PLUG(S)// UNIT MENDAPAT CASHBACK 3.000.000																	
55	DB 1028 QP	TOYOTA AVANZA 1.3G	2013	MT	1298	PUTIH	RP. 71.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI LUWUK BANGGAI CAB. LUWUK BANGGAI, JALAN TRANS SULAWESI, KOYAOAN PERMAI // MESIN BERFUNGSI, ALARM TIDAK ADA, BODY TERGORES, SPARKBOARD TIDAK ADA, MESIN REMBES OLI.BUMPER REPLACE (RR), DOOR REPAIR (TRUNK), FENDER REPAIR (FR-R), SIDE SKIRT REPAIR (R), ROOF REPAIR, LICENSE PLATE, EMBLEM, SPOILER (RR), FENDER REPAIR (FR-L), TURN LAMP (FR-R), WINDSHIELD WIPER, FOG LAMP (R), RIM COVER (FR-R), RIM COVER (FR-R), RIM COVER (FR-R), RIM COVER (FR-R), RIM COVER (FR-R), RIM COVER (FR-R), RIM COVER (FR-R), RIM COVER (FR-L), MIRROR (R), RIM COVER (FR-L), FOG LAMP (L), HEADLIGHT (FR-L), MIRROR (L), TURN LAMP (FR-L)CARPET FLOOR (FR-L), HORN, CARPET FLOOR (MID), INTERIOR SALOON, HEAD UNIT, CARPET, GEAR LEVER COVER, BOLT CRANE AND JACK, CARPET FLOOR (RR), TOOL KIT, CARPET FLOOR (FR-R), STEERING-WHEELTIRE (RR-R), AIRBAG, TIRE (FR-R), TIRE (FR-L), RIM (SPARE), RIM (RR-L), TIRE (SPARE), RIM (FR-R), RIM (FR-L), RIM (RR-R), SPRING (FR), SPRING (RR), RACK STEER, CLUTCH PLATE, CLUTCH BEARING, TIRE (RR-L), ENGINE SERVICES (LIGHT), AIRBAG SENSOR, FAN BELT, REMOTE, RADIATOR, SHOCBREAKERS (RR), AIRCON EVAPORATOR, RADIATOR FAN, BRAKE MASTER, SHOCBREAKERS (FR), SPARK PLUG(S), BRAKE PAD (FR), BATTERY, BRAKE PAD (RR)// UNIT MENDAPAT CASHBACK 3.000.000																	
56	DT 8234 AA	SUZUKI CARRY PU	2021	MT	1462	HITAM	RP. 77.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI BAU-BAU JL. GAJAH MADA NO. 141, KEL. TANGANAPADA, KEC. MURHUM, BAU-BAU // MESIN BERFUNGSI, BODY TERGORES, BAK BARET.WINDSHIELD WIPER, TAILLIGHT (RR-L), TURN LAMP (FR-L), ROOF REPAIR, DOOR REPAIR (FR-R), RIM COVER (FR-L), RIM COVER (RR-R), FRONT PANEL REPAIR, CARGO PANEL REPAIR (RR), TURN LAMP (FR-R), TAILLIGHT (RR-R), TURN LAMP (RR-L), TURN LAMP (RR-R), RIM COVER (RR-L), RIM COVER (FR-R), CARGO PANEL REPAIR (DECK), HEADLIGHT (FR-L), HEADLIGHT (FR-R), BUMPER REPAIR (FR)BOLT CRANE AND JACK, INTERIOR SALOON, CARPET, TOOL KIT, SUNVISOR (L)SPRING (RR), SPRING (FR), FAN BELT, SPARK PLUG(S), CLUTCH PLATE, BRAKE PAD (RR), RIM (SPARE), TIRE (FR-R), TIRE (FR-L), RIM (FR-R), RIM (FR-L), AIR FILTER, RIM (RR-L), TIRE (RR-L), BATTERY, BRAKE PAD (FR), TIRE (SPARE), TIRE (RR-R), ENGINE SERVICES (LIGHT), RIM (RR-R)// UNIT MENDAPAT CASHBACK 3.000.000																	
57	DN 1773 DG	DAIHATSU XENIA	2008	MT	1298	SILVER METALIK	RP. 53.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI TOLI-TOLI CAB. TOLI-TOLI, JL. BANGAU, KEL. TULUWEY, KEC. BAOLAN, TOLITOLI // MESIN BERFUNGSI, BODY TERGORES, MESIN REMBES OLI, SPARKBOARD DEPAN TIDAK ADA.RIM COVER (RR-L), EMBLEM, TURN LAMP (RR-R), RIM COVER (FR-R), WINDSHIELD WIPER, SIDE SKIRT REPAIR (R), DOOR REPAIR (TRUNK), SIDE SKIRT REPAIR (L), TURN LAMP (RR-L), HEADLIGHT (FR-L), TAILLIGHT (RR-R), RIM COVER (FR-L), MIRROR (L), RIM COVER (RR-R), TURN LAMP (FR-R), BUMPER REPAIR (RR), HEADLIGHT (FR-R), TAILLIGHT (RR-L), TURN LAMP (FR-L), MIRROR (R), BUMPER REPLACE (FR)SEATBELT (RR-L), SEATBELT (RR-R), CARPET FLOOR (MID), INTERIOR SALOON, BOLT CRANE AND JACK, CARPET FLOOR (FR-L), CARPET FLOOR (RR), CARPET FLOOR (FR-R), TOOL KIT, CARPETAIRCON EVAPORATOR, RIM (RR-R), SHOCBREAKERS (FR), TIRE (RR-R), TIRE (RR-L), BRAKE PAD (RR), BATTERY, SPRING (RR), RIM (RR-L), TIRE (FR-L), CLUTCH PLATE, BRAKE MASTER, TIRE (SPARE), RIM (FR-L), WHEEL BEARING (RR), RACK STEER, ENGINE SERVICES (LIGHT), RIM (FR-R), RIM (SPARE), SHOCBREAKERS (RR), WHEEL BEARING (FR), BRAKE PAD (FR), SPARK PLUG(S), TIRE (FR-R), CLUTCH BEARING, SPRING (FR), FAN BELT // FOTO NOKA 4DIGIT TIDAK JELAS// UNIT MENDAPAT CASHBACK 3.000.000																	
58	DD 1096 BV	TOYOTA AVANZA VELOZ	2014	MT	1495	HITAM METALIK	RP. 0	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI TERNATE CAB. TERNATE, LORONG JERUK RT/RW 007/002 KEL. UBO-UBO KEC TERNATE SELATAN KOTA TERNATE MALUKU UTARA // RIM COVER (FR-R), HEADLIGHT (FR-L), DOOR REPAIR (RR-R), TURN LAMP (FR-R), EMBLEM, BUMPER REPAIR (RR), DOOR REPAIR (FR-R), RIM COVER (FR-L), RIM COVER (RR-L), TURN LAMP (FR-L), DOOR REPAIR (TRUNK), FOG LAMP (L), DOOR REPAIR (RR-L), FOG LAMP (R), BUMPER REPAIR (FR), ENGINE HOOD REPAIR, DOOR REPAIR (FR-L), RIM COVER (RR-R), HEADLIGHT (FR-R)STEERING-WHEEL, DASHBOARD, TOOL KIT, CARPET, INTERIOR SALOON, HEAD UNIT, BOLT CRANE AND JACKCOIL IGNITION, CLUTCH PLATE, HEADER, INJECTOR, RADIATOR FAN, RIM (RR-L), RIM (FR-L), RADIATOR, WHEEL BEARING (FR), ENGINE MOUNTING, POWER STEERING, AIRBAG, SPRING (FR), SPARK PLUG(S), SPRING (RR), CLUTCH BEARING, GASKET CYLINDER HEAD, BRAKE PAD (RR), TIRE (RR-L), ENGINE SERVICES (HEAVY), WHEEL AXELS (FR), TIRE (FR-L), WHEEL AXELS (RR), BATTERY, RIM (FR-L), RIM (RR-R), SHOCBREAKERS (RR), FAN BELT, SHOCBREAKERS (FR), RACK STEER, DYNAMO STARTER, TIRE (FR-R), WHEEL BEARING (RR), BRAKE PAD (FR), AIRCON EVAPORATOR, ENGINE SERVICES (LIGHT), GASKET COVER HEAD, TIRE (SPARE), TIRE (RR-R)																	
59	DG 1208 UT	SUZUKI IGNIS	2019	MT	1197	BIRU METALIK	RP. 91.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI TERNATE CAB. TERNATE, LORONG JERUK RT/RW 007/002 KEL. UBO-UBO KEC TERNATE SELATAN KOTA TERNATE MALUKU UTARA // FENDER REPAIR (FR-R), FENDER REPAIR (FR-L), DOOR REPAIR (TRUNK), BUMPER REPAIR (FR), DOOR REPAIR (RR-L), DOOR REPAIR (FR-L), DOOR REPAIR (RR-R), BUMPER REPAIR (RR), DOOR REPAIR (FR-R)BOLT CRANE AND JACK, TOOL KIT, INTERIOR SALOON, CARSEAT (FR-L), CARSEAT (FR-R)SPRING (RR), GASKET CYLINDER HEAD, ENGINE SERVICES (HEAVY), SPRING (FR), COIL IGNITION, HEADER, RADIATOR FAN, TIRE (RR-R), GASKET COVER HEAD, TIRE (FR-R), TIRE (RR-L), CLUTCH BEARING, TIRE (FR-L), SHOCBREAKERS (FR), CLUTCH PLATE, SPARK PLUG(S), FAN BELT, SHOCBREAKERS (RR), WHEEL AXELS (RR), RADIATOR, AIRCON EVAPORATOR, WHEEL AXELS (FR), BRAKE PAD (RR), BRAKE PAD (FR), BATTERY// UNIT MENDAPAT CASHBACK 3.000.000																	
60	DG 1732 KB	TOYOTA AVANZA 1.3G	2011	MT	1298	SILVER METALIK	RP. 47.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI TERNATE CAB. TERNATE, LORONG JERUK RT/RW 007/002 KEL. UBO-UBO KEC TERNATE SELATAN KOTA TERNATE MALUKU UTARA // EMBLEM, FENDER REPAIR (FR-R), LICENSE PLATE, FENDER REPAIR (FR-L), HEADLIGHT (FR-R), TURN LAMP (RR-L), TURN LAMP (RR-R), RIM COVER (RR-L), HEADLIGHT (FR-L), RIM COVER (RR-R), DOOR REPAIR (FR-R), TURN LAMP (FR-L), RIM COVER (FR-L), ROOF REPAIR, TAILLIGHT (RR-R), BUMPER REPAIR (RR), DOOR REPAIR (RR-L), RIM COVER (FR-R), FOG LAMP (R), DOOR REPAIR (FR-L), TURN LAMP (FR-R), DOOR REPAIR (TRUNK), FOG LAMP (L), BUMPER REPAIR (FR)CARSEAT (M-R), STEERING-WHEEL, CARSEAT (M-L), CARSEAT (RR-R), CARSEAT (RR-L), HEADREST (RR-R), HEADREST (M-L), HEADREST (FR-L), HEADREST (RR-L), HEADREST (M-R), HEADREST (FR-R), BOLT CRANE AND JACK, INTERIOR SALOON, CARPET, TOOL KIT, HEAD UNIT, DASHBOARDREMOTE, CHECK ENGINE INDIKATOR, RIM (FR-L), RIM (FR-R), RIM (RR-R), RIM (SPARE), RIM (RR-L), TIRE (FR-R), MAIN AXELS, ENGINE MOUNTING, POWER STEERING, SHOCBREAKERS (FR), WHEEL BEARING (FR), BRAKE PAD (FR), WHEEL AXELS (RR), RADIATOR, INJECTOR, RACK STEER, WHEEL BEARING (RR), SPARK PLUG(S), TIRE (SPARE), RADIATOR FAN, HEADER, TIRE (FR-L), BRAKE PAD (RR), CLUTCH PLATE, TIRE (RR-L), FAN BELT, GASKET CYLINDER HEAD, GASKET COVER HEAD, MUFFLER, SPRING (FR), WHEEL AXELS (FR), SHOCBREAKERS (RR), CLUTCH BEARING, TIRE (RR-R), SPRING (RR), BATTERY, AIRCON EVAPORATOR, ENGINE SERVICES (HEAVY), COIL IGNITION // ADA PERBEDAAN WARNA FISIK SILVER HITAM PADA DOKUMEN SILVER METALIK// UNIT MENDAPAT CASHBACK 3.000.000																	
61	PB 1939 SH	MITSUBISHI XPANDER 1.5L	2021	MT	1499	HITAM MIKA	RP. 220.000.000	BENSIN	0	-	-	-	9 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN
UNIT TIDAK DICEK SECARA LANGSUNG OLEH TEAM SMARTBID // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //HARAP MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT // PERMASALAHAN YANG DITIMBULKAN DILUAR TANGGUNG JAWAB SMARTBID // PENGAMBILAN UNIT H+2 SETELAH PELUNASAN // UNIT BERADA DI SORONG CAB. SORONG JL. SAPTA TARUNA KM 10 KEL.SAWAGUMU SORONG PAPUA // BUMPER REPAIR (RR) , BUMPER REPAIR (FR) , ENGINE HOOD REPAIRBOLT CRANE AND JACK , TOOL KIT , INTERIOR SALOONCOIL IGNITION , HEADER , ENGINE SERVICES (LIGHT) , SPRING (FR) , BRAKE PAD (FR) , BRAKE PAD (RR) , SHOCBREAKERS (FR) , BATTERY , SPARK PLUG(S) , TIRE (FR-L) , TIRE (RR-R) , CLUTCH PLATE , TIRE (FR-R) , SPRING (RR) , SHOCBREAKERS (RR) , TIRE (SPARE) , TIRE (RR-L) , FAN BELT// UNIT MENDAPAT CASHBACK 3.000.000															